



AZIMUTH GROUP INTERNATIONAL LTD
AZIMUTH COMPANY
INSPECTION DEPARTMENT

Web.: www.azimuth-iq.com
Email: info@azimuth-iq.com
Contact: +964 750 138 5358
+964 772 417 1777
Villa #194, pank city
Old Baharka Road, Erbil, KRG-Iraq

CLIENT NAME:	Lautki Shawk Company
LOCATION:	Work Site
EQUIPMENT NAME:	FRONT WHEEL LOADER

CERTIFICATE NUMBER:	AZI-25-245-005
----------------------------	-----------------------



Corporate Partner



AZIMUTH GROUP INTERNATIONAL LTD
AZIMUTH COMPANY
INSPECTION DEPARTMENT

Web.: www.azimuth-iq.com
Email: info@azimuth-iq.com
Contact: +964 750 138 5358
+964 772 417 1777
Villa #194, pank city
Old Baharka Road, Erbil, KRG-Iraq

FITNESS CERTIFICATE

CERTIFICATE NUMBER	AZI-25-245-005
CLIENT NAME	Lautki Shawk Company
WORK LOACATION	Work Site

DATE	August 13, 2025
Ref Standrad	EN 474:2006

SUBJECT: INSPECTION OF FRONT WHEEL LOADER

This is to certify that the under signed, a competent representative did attend to examine this equipment to ascertain the safe working condition of the equipment. At the time of examination indicated, the said equipment has no indigenous injury or sighted deformation. The equipment is safe for its intended use within the limits specified, provided there is a continuous maintenance applied and qualified operators employed.

DETAILS OF EQUIPMENTS:

DESCRIPTION	FRONT WHEEL LOADER	MANUFACTURER	VOLVO
CHASSISS NUMBER	L120CV62545	SERIAL NUMBER	L120CV62545
REGISTRATION NUMBER	N/A	MODEL & YEAR	L120C/2010

OBSERVATION

The above equipment and its accessories were visually inspected and found to be Satisfactory for further use. All the safety devices and warning lights were working satisfactory. Inspection carried out and report issued with out prejudice to the rights of whomsoever it may concern for and on behalf of Azimuth Inspection Services.

DATE OF LAST EXAMINATION

--

DATE OF NEXT EXAMINATION

August 12, 2026

Examiner Name:

Ghassan Al-Gallani

Examiner Signature:



Authorized name

M. Safah

Authorized Signature:



THIS IS TO CERTIFY THAT the above signed competent surveyor has thoroughly and visually examined equipment in the above-mentioned place as per relevant standard. The liabilities and insurance is as per Azimuth Inspection Services.



Corporate Partner



AZIMUTH GROUP INTERNATIONAL LTD
AZIMUTH COMPANY
INSPECTION DEPARTMENT

Web.: www.azimuth-iq.com
Email: info@azimuth-iq.com
Contact: +964 750 138 5358
+964 772 417 1777
Villa #194, pank city
Old Baharka Road, Erbil, KRG-Iraq

CERTIFICATE NUMBER	AZI-25-245-005	DATE OF INSPECTION	August 13, 2025
--------------------	-----------------------	--------------------	------------------------

NO	DESCRIPTION	CONDITION	REMARKS
1	POWER UNIT	SATISFACTORY	--
2	OPERATORS CABIN	SATISFACTORY	--
3	INDENTIFICATION ON CONTROLS LEVERS	SATISFACTORY	--
4	HYDRAULIC ATTACHMENTS	SATISFACTORY	--
5	ELECTRICAL SYSTEM	SATISFACTORY	--
6	LIGHTINGS, HORNS	SATISFACTORY	--
7	HYDRAULIC SYSTEM	SATISFACTORY	--
8	WINDSHIELDS / MIRRORS	SATISFACTORY	--
9	SWING MECHANISM	N/A	--
10	BRAKES SYSTEM	SATISFACTORY	--
11	CRAWLER / TYRES/DRUM	SATISFACTORY	--
12	CONTROL LEVERS	SATISFACTORY	--
13	ROTATING WARNING LIGHT	SATISFACTORY	--
14	REVERSE HORN	SATISFACTORY	--
15	FIRE EXTINGUISHER	SATISFACTORY	--
16	EXHAUST SYSTEM	SATISFACTORY	--
17	SAFETY MARKINGS	SATISFACTORY	--
18	BUCKETCONDITION	SATISFACTORY	--
19	GENERAL CONDITION	SATISFACTORY	--

COMMENTS	NEED TO BE PROPER CLEANING ON DAILY BASIS
-----------------	--

Examiner Name:

Ghassan Al-Gailani



Examiner Signature:



Corporate Partner



AZIMUTH GROUP INTERNATIONAL LTD
AZIMUTH COMPANY
INSPECTION DEPARTMENT

Web.: www.azimuth-iq.com
Email: info@azimuth-iq.com
Contact: +964 750 138 5358
+964 772 417 1777
Villa #194, pank city
Old Baharka Road, Erbil, KRG-Iraq

CERTIFICATE NUMBER AZI-25-245-005

DATE OF INSPECTION August 13, 2025



Examiner Name:

Ghassan Al-Gailani



Examiner Signature:



Corporate Partner