



AZIMUTH GROUP INTERNATIONAL LTD
AZIMUTH COMPANY
INSPECTION DEPARTMENT

Web.: www.azimuth-iq.com
Email: info@azimuth-iq.com
Contact: +964 750 138 5358
+964 772 417 1777
Villa #194, pank city
Old Baharka Road, Erbil, KRG-Iraq

CLIENT NAME	ASTYARI RE COMPANY
WORK LOCATION	WORK LOCATION
EQUIPMENT NAME	PNEUMATIC TYRE ROLLER

CERTIFICATE #	AZI-25275-004
----------------------	----------------------



AZIMUTH Co.
M.Salah
Certified Inspector

INSPECTION
DEPARTMENT
AZIMUTH





FITNESS CERTIFICATE

CERTIFICATE NUMBER	AZI-25275-004	DATE	September 16, 2025
CLIENT NAME	ASTYARI RE COMPANY	Ref Standrad	EN 474:2006
WORK LOACATION	WORK LOCATION		

SUBJECT: INSPECTION OF PNEUMATIC TYRE ROLLER

This is to certify that the under signed, a competent representative did attend to examine this equipment to ascertain the safe working condition of the equipment. At the time of examination indicated, the said equipment has no indigenous injury or sighted deformation. The equipment is safe for its intended use within the limits specified, provided there is a continuous maintenance applied and qualified operators employed.

DETAILS OF EQUIPMENTS:

DESCRIPTION	PNEUMATIC TYRE ROLLER	MANUFACTURER	SAKAI
CHASSISS NUMBER	10137	SERIAL NUMBER	10137
REGISTRATION NUMBER	598079 BAGHDAD	MODEL & YEAR	T600-A /1998

OBSERVATION

The above equipment and its accessories were visually inspected and found to be Satisfactory for further use. All the safety devices and warning lights were working satisfactory. Inspection carried out and report issued with out prejudice to the rights of whomsoever it may concern for and on behalf of Azimuth Inspection Services.

DATE OF LAST EXAMINATION

DATE OF NEXT EXAMINATION
 September 15, 2026

Examiner Name:

M.SALAH

Examiner Signature:

(Handwritten signature of M. Salah)
 AZIMUTH Co.
 Certified Inspector

Authorized name

Majdi Ahmad

Authorized Signature:

(Handwritten signature of Majdi Ahmad)
 INSPECTION DEPARTMENT

THIS IS TO CERTIFY THAT the above signed competent surveyor has thoroughly and visually examined equipment in the above mentioned place as per relevant standard. The liabilities and insurance is as per Azimuth Inspection Services.





CERTIFICATE NUMBER **AZI-25275-004**

DATE OF INSPECTION **September 16, 2025**

NO	DESCRIPTION	CONDITION	REMARKS
1	POWER UNIT	SATISFACTORY	--
2	DRIVE SYSTEM	SATISFACTORY	--
3	INDENTIFICATION ON CONTROLS LEVERS	SATISFACTORY	--
4	HYDRAULIC ATTACHMENTS	SATISFACTORY	--
5	ELECTRICAL SYSTEM	SATISFACTORY	--
6	LIGHTINGS, HORNS	SATISFACTORY	--
7	HYDRAULIC SYSTEM	SATISFACTORY	--
8	BRAKES SYSTEM	SATISFACTORY	--
9	STEERING OPERATION	SATISFACTORY	--
10	VIBRATION SYSTEM	SATISFACTORY	--
11	CRAWLER / TYRES / DRUM	SATISFACTORY	--
12	CONTROL LEVERS	SATISFACTORY	--
13	EMERGENCY SWITCH	SATISFACTORY	--
14	DRIVEN DRUM	SATISFACTORY	--
15	FIRE EXTINGUISHER	SATISFACTORY	--
16	EXHAUST SYSTEM	SATISFACTORY	--
17	SAFETY MARKINGS	SATISFACTORY	--
18	ROLLER CONDITION	SATISFACTORY	--
19	GENERAL CONDITIONS	SATISFACTORY	--

COMMENTS: NEED TO BE PROPER CLEANING ON DAILY BASIS

Examiner Name: **M.SALAH**

Examiner Signature:



Corporate Partner



AZIMUTH GROUP INTERNATIONAL LTD
AZIMUTH COMPANY
INSPECTION DEPARTMENT

Web.: www.azimuth-iq.com
Email: info@azimuth-iq.com
Contact: +964 750 138 5358
+964 772 417 1777
Villa #194, pank city
Old Baharka Road, Erbil, KRG-Iraq

CERTIFICATE NUMBER AZI-25275-004

DATE OF INSPECTION September 16, 2025



Examiner Name: M. SALAH



Examiner Signature:

